

## Note -

Go to "Property" of Printer, click "Ports" page,

Please **unmark** or **disable** bidirectional support. Some printers might stay at wait state for one minute after printing is done if bidirectional support is enabled.

Click **OK** to exit.

